



Botao Sun <botao.sun@linaro.org>

Test Result Summary of Calendar Week 7, 2013 for Linux Linaro ubuntu Quantal.

Botao Sun <botao.sun@linaro.org>
To: linaro-release <linaro-release@lists.linaro.org>
Cc: linaro-dev <linaro-dev@lists.linaro.org>

Thu, Feb 14, 2013 at 4:44 PM

Calendar Week 7, 2013: Here is test result summary for Linux Linaro ubuntu Quantal image on following boards:

- 1) ARM Versatile Express A9;
- 2) Samsung Arndale;
- 3) TI Panda 4430;
- 4) TI Panda 4460;
- 5) ST Ericsson Snowball.

Synopsis: All boards keep exactly same status as last week, except Samsung Arndale. Device Tree is only available on Samsung Arndale.

1. ARM Versatile Express A9 + Linux Linaro Quantal (Column K):

<https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdFNmV3gyZWRGVS12YUhqeW9rdkVZdmc#gid=1>

It keeps exactly same status from calendar 50 last year: only "Halt" & "Device Tree" test failed, all other features work well.

2. Samsung Arndale + Linux Linaro Quantal (Column E):

<https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AgB-fT5LL31CdGZJSFdTUWFFYVdhZl8wMFpxLXd2TXc#gid=0>

Ethernet failed this week, and it blocked ARM DS-5 and Power Management test. No display via HDMI interface. Other features work well.

3. TI Panda 4430 + Linux Linaro Quantal (Column K):

<https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdEwwZkhrZ1VYUEg2LTIQZzR0RlhzM3c#gid=3>

It keeps exactly same status as last week: only Device Tree is unavailable.

4. TI Panda 4460 + Linux Linaro Quantal (Column K):

<https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdEwwZkhrZ1VYUEg2LTIQZzR0RlhzM3c#gid=4>

It keeps exactly same status as last week: only Device Tree is unavailable.

5. ST Ericsson Snowball + Linux Linaro Quantal (Column K):

<https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdFJ4X0NjWjJteVIXLVJFSHFuOHo1c2c#gid=1>

It keeps exactly same status as last week: no Ethernet, HDMI display, Device Tree, "Reboot" failed, and Power Management test will cause Kernel Panic. Also, ARM DS-5 is blocked because no network connection available.